

T33S, R6W, W.M., Section 7

Renewal of East 1/16 Cor. ~~Sec. 6~~
Sec. 7

I find brass cap on 2" G.I. Pipe as set in U.S. B.L.M.
1964 Survey and 1 B.T. with scribe visible:

A 10" D. Fir, N 14°W, 20.8' (Rec. 21.1') The
Southwest B.T. has been obliterated by road
construction.

I scribe a new B.T.,
an 18" D. Fir, S 61°E 95.9'
scribed "3683 1/16 S7BT"

This corner lies just off the Northerly edge of a
newly constructed forest road switchback, running
Northerly, Westerly, and Southerly.

Done for Superior
Logging Co., P.O. Box
250, Glendale, Oregon

February 22, 1967



#29 posted

ROAD LOCATIONS • TRACT DEVELOPMENT AND DESIGN • LAND SURVEYING
FOREST MANAGEMENT • TIMBER CRUISING AND APPRAISAL

C. S. File No. 55/27