



# THE ROBERT DOLLAR CO.

## FOREST PRODUCTS DIVISION

AREA CODE 503

TELEPHONES

OFFICE 832-5050 SALES 832-5820

GLENDALE, OREGON

October 1, 1968

HEAD OFFICE  
311 CALIFORNIA STREET  
SAN FRANCISCO 4

*RECEIVED*  
*COPIES*

County Surveyors Office  
Douglas County Courthouse  
Roseburg, Oregon

Dear Sir:

I have found the following at the 1/4 Section Corner common to Sections 5 and 6, Township 32 South, Range 5 West, W.M.:

- Sawed Cedar Stump 30", S 41° E, 37 LKS
  - Sawed Cedar Stump 32", N. 19° W, 51 LKS
  - Fir BT 6", S 88° E, 38½ LKS Good Condition
  - Fir BT 10", N 78° W, 54 LKS Good Condition but  
face covered by log pile.
- Brass Cap and Iron Pipe removed by logging operation.

For the corner I have set a 1" by 42" iron rod 36" in the ground. I have rescribed the 10" Fir above the log pile. The scribing reads 1/4 S., R.S. 749 BT.

All bearings were taken with a staff compass, Magnetic Variation 20° E. Distances were measured with a steel tape. This corner was witnessed by Marvin Van Norman.

Very truly yours,

THE ROBERT DOLLAR CO.

Thomas H. Mehl, III  
Registered Surveyor 749

FILED  
RECEIVED

THM:mt

OCT 4 1968

COUNTY SURVEYOR  
DOUGLAS COUNTY, OREGON

#177

C. S. File No. 55/91