



P. O. Box 1328 • Roseburg, Oregon 97470 • Phone 672-3331

January 17, 1969

Mr. James Byron  
Douglas County Surveyor  
Douglas County Courthouse  
Roseburg, Oregon 97470

Dear Mr. Byron:

I have checked the field notes on the survey for the recently filed plat of Section 20, Township 24 South, Range 1 West, and found the following errors and omissions.

1.  $\frac{1}{4}$  Corner Sections 19 and 20, Township 24 South, Range 1 West  
No Monument Set
2.  $\frac{1}{4}$  Corner Sections 20 and 29, Township 24 South, Range 1 West  
No Monument Set  
Distance to bearing trees reversed

Correction:

- 14" Cedar, N 3°W, 19.9 Ft.
- 26" Fir, S 65°E, 9.1 Ft.

3.  $\frac{1}{4}$  Corner Sections 20 and 21, Township 24 South, Range 1 West  
Found: Brass Cap 1961

*BOZ - CHANGE THIS ON TRACING*

Yours very truly,

*Tom Shrum*

Tom E. Shrum, Engineer  
ROSEBURG OPERATIONS

TES:cs

C.S File 55/105

Map File M37 p. 2