

REPORT OF SURVEY CORNERS

Twp. 20 S. Rge. 11 W. W.M. Douglas County _____ Date June 2, 1969

Corner Found 1/4 Section corner between Sections 23 and 24 Run #36

Evidence of Corner Found Pipe with Brass Cap - 1964 and 2 B.Ts. with Metal Tags

Corner Location in Reference to Terrain and Cover In steep S80°W sloping gulley
Approximately 10 feet on South side from "V" of gulley--- Approximately
550 feet down from road on Top Ridge.

BEARING TREES

Quadrant	NE	SE	SW	N.E. SW
Species & Size	Red Cedar 26" D.B.H.	14" 11 B.B.H.		Red Cedar 28" D.B.H.
Dist. and Brg. From Corner	N12°E 29 Feet	S41°E 33.4 Feet		N45°E Approx. 40 Feet
Condition of Scribe or Scar	Original scribes plus New scribes	Chopped out Face pitched over		Chopped when looking for original B.T.
Original or Resurvey BT	Original B.T. Survey 1892	New B.T. in . 1964		Not Original No Scribes
Appearance of BT	Poor Condition	Live- Good		Live - large sweep in butt
Tags, Marks, etc. on BT	Ed. BLM Yellow Metal Tag - 4/2/63	Ed. BLM Yellow Metal Tag - 9/64		No tags- no marks

Other Information I set a cedar post with an aluminum tag on the East side
of U.S.F.S. Access Road #2059-D-- up on the road bank so it would not be
destroyed by road equipment. From this stake, go West, down a very steep
gulley approximately 550 feet, to the corner.

How Can Corner Be Best Reached Up Smith River Road; then up North Fork Smith
River Road; then on U.S.F.S. Road to U.S.F.S. Road #2059-D

**FILED
RECEIVED**

JUL 3 1969

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**

Name *Louis B. Prahar*
Louis B. Prahar, Forest Engineer
Oregon Surveyor's Certificate No. 308

LOUIS PRAHAR
FOREST ENGINEER
OREGON REGISTERED LAND SURVEYOR NO. 308
R. R. 1, BOX 518
BANDON, OREGON 97411

July 1, 1969


Mr. Jim Byron, County Surveyor
Court House
Roseburg, Oregon

Dear Jim:

Enclosed find a corner report. This is the only corner I was able to find in this area. I spent two days looking for the corner of Sections 23, 24, 25, 26, T.20S., R.11W. and the $\frac{1}{4}$ Section corner between Sections 25 and 26 ---- no luck.

I never did get over to the corner of Sections 22, 23, 26 and 27, T.20S., R.11W. so cannot report on it.

Sincerely,



File No. 55/117