



THE ROBERT DOLLAR CO.

FOREST PRODUCTS DIVISION

TELEPHONES

Area Code 503

OFFICE: 832-2111 SALES: 832-2131

GLENDAL, OREGON 97442

HEAD OFFICE
311 CALIFORNIA STREET
SAN FRANCISCO 94104

November 17, 1972

FILED
RECEIVED

NOV 2 11972

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Mr. Ingram, County Surveyor
Douglas County Courthouse
Roseburg, Oregon 97470

Dear Mr. Ingram:

During our logging operation on a State of Oregon timber sale the past summer it resulted that the two original bearing trees were completely destroyed. The brass cap was found intact, but the pipe was bent. The corner is described by the following:

FOUND - Brass Cap, set by Douglas County Surveyor 1959 on the $\frac{1}{4}$ Corner, Sec. 7, T. 32 S., R. 5 W. and Sec. 12, T. 32 S., R. 6 W. *REN # 117 # 59*

DESTROYED - the original bearing trees

1. a 44" I. Cedar, S 11' E, 33.3 ft.
2. a 36" I. Cedar, S 81' W, 16.8 ft.

EQUIPMENT-

Gurley Staff Compass
Variation 19° 45' E.
200 ft. Eng. chain

New bearing trees which bear from the brass cap -

1. a 5.52" D.F., S 68° 15' W, 31.05 ft.
mkd. $\frac{1}{4}$ S 12 PS 841 B.T.
2. a 9.55" D.F., N 06° 40' E, 16.76 ft.
mkd. $\frac{1}{4}$ S 7 PS 841 B.T.

The pipe and brass cap were removed, the pipe straightened and then re-set in its initial position. The tree measurements are at DBH and horizontal distance from monument to the center of the scribed face.

Very truly,
THE ROBERT DOLLAR CO.

Ronald A. Brandt
Forest Engineer

RAB/jrr

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Brandt

OREGON
JULY 12, 1968
RONALD A. BRANDT
841

T 32-6 # 127 ✓
T 32-5 # 187 ✓

C. S. File No. 55/257-1