

✓
Mander Car $\frac{2^B}{33}$ on West side of slough.
M.C. cor to the West apparently
gone.

This Iron pipe was Tied by
INT. Net Paper. FD brushing but
No cor. Pipe was NOT Referenced.

✓
Cor. FD. (Apprent) D26[#]37 S.W. Cor.

This Point $\frac{7}{8}$ " I Rod Flush with
concret, in driveway on the East
side of Highway 101.

No Trace of Alder BTs. (1925)

#36

D. H.
J. H. G.

CS56 17-5