

Renewal # 11 25/30 36/31 T215 B7-6W

Found:

36" D. Fir N72W 53 3/4
Bark Scribed
30" D. Fir N40W 60 6/8
Bark Scribed

6 Hemlock S82E 112

ALSO ^{HAINES'} Iron at sec cor.

Renewal

New Bearing Trees

10" D. Fir S19W 125
Scribed T215 R7W S36 CS BT

5" D. Fir S28E 37 2/3
Scribed S31 CS BT.

There is to be a Road near this cor. Mt. cor. Regulated.

I do not set Mt. cor. because I do not know where the Rd is going to go. (It is not stated) Preliminary grade (?) P. b. lions are above cor by 50-60 ft.

Possibly N40W BT will be destroyed.

(Ren. # 43-T21-7)

#94T21-7
#125-T21-6

4-12-72
J. H. S.
10.31

OK.
F. L. L.

C. S. File No. 56/12-7