

sec. cor 5 24-25 7 19 ency

Renewal $\frac{524}{525}$ | S30 T215 R9-BW

Found: 26" Fir stump

N80°E 63 $\frac{1}{4}$ ' Open For

Scribing B.T.

48" Fir ^{STUMP} N33°W 143 $\frac{1}{2}$ '

also: Brass cap C.C. Marked

U.S.G.L.O.S.

	T215	T215
	S24	R8W
- CC	$\frac{525}{525}$	S30
	R9W	
	1945	

also: 1" iron pipe along side B.C.

Renewal new B.T.

6" D. Fir N31°W 11 $\frac{3}{4}$ '

Scribed S24 CS BT

8" D. Fir South 29 $\frac{1}{2}$ '

Scribed S25 CC CS BT
(OVER)

#20 T91-8
#23 T21-9

12-52/55-21
= CC 54/55-21

Note: This corner lies
in old clear cut very
brushy. a lot of new
growth. IT lies on
westerly slope approx.
60' westly of ridge top.

5-11-73

JMP
GEC

OK JLL

DIETZGEN NO. 385-S

C. S. File No. 56/25-21