

Renewal  $\frac{21}{28}$  T26S R1W

Found:

5" Fir down + Rotten S86E  $2\frac{6}{8}$

scribe visible s 28

Also 5x8x6 stone MKD  $\frac{1}{4}$

on North Face firmly in ground.

No Trace of NW BT,

Renewal

Set Brass cap at  $\frac{1}{4}$  cor MKD

County Surveyors office

T26S R1W

$\frac{1}{4}$   $\frac{21}{28}$

1973

New Bearing Trees.

20" D. Fir N70E  $9\frac{2}{8}$

scribed  $\frac{1}{4}$  s 21 cs BT

18" D. Fir S5E  $25\frac{4}{8}$

scribed  $\frac{1}{4}$  s 28 cs BT,

#67 ✓ O.K. 5-21-77  
C.S. File No. 56/25 ~~JKR~~ -28 ~~JKR~~