

Repair S.W. COR. of DLF, #54 T225 R8W
Fd. Both 1964 cad. B.T.s - 2 live
& in good cond. - Fir Healed -
cedar has scribe visible on
partially healed Blaze. 1964
Cad. Brass cap was fd. in
creek bottom. We Reset at
The cor. point & also Reset
steel fence post along side.
This cor. lies on East
Bank of small creek, coarse
North & in very dense underbrush.

July 12, 1973
✓ #127

V.R.T.
J.G.H.

Fd. O.K. T225 R8W

$\frac{1}{4} \frac{528}{533}$ - Cad. Brass cap

& B.T.'s, all in good cond.

July 12, 1973

V.R.T.
J.G.H.

O.K. [Signature]

004R

C.S. File No. 56/34-4

T225 R8W

Fd. O.K. Int. "L" [DLC 44,

1964 D.C.S. B.C. & B.T.S O.K.

See Ren. # 115

July 12, 1973

VRT
JGH