

Renewal #119524.1 33/34 T245 R7W
#105125.1 T255

Found

6" Dia Bed set Fir only at sec cor

Fir stump N61E 72"
shows good scar

17" D. Fir N61W N20W 21"
shows good scar

I do not open trees as every
thing fits as noted

Renewal

32" D. Fir N21E 582
scribed T245 R7W 534 CS. RE ST

*123 T24.1 ✓
*107 T25.1 ✓

12-17-70
~~9/25~~

7-3-73

U.R.T. & J.G.H. arrived at the
above sec. cor. at approx same
time as Cad. Egg's who are
making Dependant Resurvey in
that area & will Reset cor. of

533 T245
54 | 53 T255 R7W in near future.

We did not Renew!

C.S. File No. 5634-SURT,
(over)

DIETZSEN NO. 385-B

~~_____~~ JMO

T245
95.7

1/4 33/37

Had fair line from
Sec cor to south
very foggy + Heavy rain -
cor may be here.

Best time to reach
is in dry weather,

12-14-70

JMO

7-3-73

N.F. 1/4 54/53 T245 R9W

NO B.T.'s - 2" squared Post

Fd. - Fairley New - I have
searched for this cor. before
some 7 or 8 years ago.

V.R.T.
J.G.H.

201

O.K.
JMO