

Renew $\frac{1}{4}$ COR. 516/515 T255 R2W

No Trace of BRASS cap at COR.

See Ren. #5 & #74 - Fd. B.T.'s

As follows -

15" maple N. 49° E 44 $\frac{1}{2}$ ft.

Alive - scribe visible - (Ren. #5)

19" maple west 52 $\frac{1}{2}$ ft.

Alive - Blaze healed. (Ren. #5)

18" cedar S. 32° W. 109 $\frac{1}{2}$ ft.

Alive - scribe visible (Ren. #74)

17" maple N. 29° E. 32° ft.

Alive - scribe visible (Ren. #74)

at COR. point set New BRASS CAP.

Mkd. " COUNTY SURVEYORS

OFFICE 1973 T255 $\frac{1}{4}$ 516/515

R2W" - This COR. lies

60 ft. west of Rock Creek

& 280 ft. south of Rock Creek

Road. - Creek & Road course

S.W.

July 25, 1973

URT
JGH

#93 ✓

OK JGH

C. S. File No. 56/34-6

Fd. O.K. 5

T245 RIW - 1/4 530/529

DCS-B.C. & B.T.S. - Ren. # 87 Fd.

O.K. 2 ft + 11 Logging ✓
7-25-73

Fd. O.K. T235 RIW & T245 RIW

Ren. # 87

533/534
54/53

DCS-B.C.

& B.T.S.

7-25-73

Fd. O.K. T245 RIW 1/4 COR 92/51

DCS B.C. & B.T.S. Ren. # 95

7-25-73 ✓

Fd. O.K. T245 RIW 1/4 54/55

DCS B.C. & B.T.S. Ren. # 96

7-25-73 ✓

M.K.D. IN
RENEWAL
BOOK. ✓