

Renew $\frac{1}{4}$ cor. 535/536 T30SR9W

Fd. 1964 D.C.S. BRASS cap in Place
& stump of orig. BT, only - see
Ren. #49 - Both Ren. BTs gone
due to Logging - We mark & Tag
New BTs -

8" W. FIR S. 10° E. 23⁶ ft.

Mkd. " $\frac{1}{4}$ 536 CS BT"

8" W. FIR S. 33° W. 56¹ ft.

Mkd. " $\frac{1}{4}$ 535 CS BT"

This cor. Lies ON South
slope approx 125⁰ ft. North of
Creek bottom - Creek course
East.

July 24, 1973

URT
JGH

OK JLL

✓
#102

C. S. File No. 56/34-12

Fd. O.K.

T305 R7W $\frac{1}{4}$ COR $\frac{22}{27}$

B.C. & B.T.S. at Rev # 85

7-24-73 ✓