

Renew $\frac{1}{4}$ cor To 514 | 513 T305 R9W

Ed. 1964 D.C.S. BRDCS CAP IN
place & ONE B.T. as follows -
(See Ren. # 52 & # 18)

20" cedar N. 73° E. 116° ft.
alive - good cond. - Scribe visible
on unhealed Blaze. - B.T. To
N.W. was destroyed by logging.

Blaze & Scribe new B.T.

6" D. Fir N. 20° W. 203 ft.
Mkd. " 145 14 C5 BT "

July 19, 1973

V.R.T.
J.G.H.

OK *J.G.H.*

#103 ✓

over

C.S. File No. 56/34-13

Fd. O.K. T305 R9W

1/4 22 1/2 23 1964 D.C.S. BC

& B.T.S' - Ren. # 46

7-19-73

Fd. O.K. T305 R9W

SEC. COR. 523 | 524 D.C.S.

526 | 525

B.C. & B.T.S Ren. # 47

7-19-73

T305 R9W

Fd. O.K. Sec. COR

535 | 536

D.C.S. B.C. & B.T.S O.K.

52 | 51

Ren. # 51 - T30-9

T315 R9W

35 - T31-9

7-19-73

Noted in Ren. Cor Book

OK J.L.

as O.K.

L.P.
L.