

Renew $\frac{1}{4}$ COR. 53/52 T305 R9W

No Trace of I.P. OR BRASS cap
fd. - See Ren. #36 & #96 -

This area appears to have
Burned again - We set new
BRASS cap MKd. "COUNTY SURVEYOR'S
OFFICE 1973 T305 $\frac{1}{4}$ 53/52
R9W" FROM Bearing objects
Recorded in Ren. #96 -

30" FIR STUMP N. 34° W. 29 ± ft,

R.R. spike driven in Top.

28" FIR STUMP N. 7° E. 32 ± ft,

R.R. spike driven in Top.

This cor. Lies 4 ± ft.
west of cat fire Road.

July 26, 1973

JRT
JGH

OK JGH

#104 ✓

C. S. File No. 56/34-14

Fd. O.K.

21/22 T30S R9W

28/27 Fd. O.K. 1965 CAD B.C.

\$ B.T.S. 7-27-73 Ren. # 23 ✓

