

Report Only - Sec. Cor. $\frac{58}{517} | \frac{59}{516}$ T305 R8W

B.T.s in Ren. # 51 O.K., except
N.E., is now stump - no other
tree close to N.E. - We
Remove Brass cap - straighten
I.P. & Reset at cor. point.

July 9, 1973

V.R.T.
T.G.H.

Fd. O.K.
Wit. Cor. T $\frac{1}{4}$ $\frac{28}{33}$ - D.C.S.B.C.
& B.T.s O.K.

Ren. # 88 7-18-73 T305 R8W

Sec. Cor. $\frac{30}{31} | \frac{29}{32}$ Fd. O.K. DCS
B.C. & B.T.s O.K. - Ren # 76
T305 R8W - 7-18-73

T305 R8W - 7-18-73
N.F. - $\frac{1}{4}$ 531 | 532 - BLM
has set I.P. by proportion.
We do not find scribe
or other evidence - also was
N.F. previously by VRT, about 9 years ago

OK JLD
S. File No. 56/34-17