

COR RENEWAL

T235 R9W
S30 S29

FOUND

2" IRON PIPE 23" ABOVE GROUND
FROM WHICH A 36" DIAM. STUMP
BEARS N30°E (Rec. N20°E) 128'

(REC 12.54 FEET)

SCRIBED

1/4 S 29 BT

OTHER BT A STUMP OUT OF GROUND
BADLY GUNED AND ROTTED STUMP
IS OUT OF GROUND AND LIES ALMOST
DIRECTLY OVER CORNER.

RENEWAL

SET BRASS CAP AT 1/4 COR INSIDE
IRON PIPE MARKED

COUNTY SURVEYORS OFFICE

T235 R9W

S30 S29

NEW BT'S AS FOLLOWS

6" D. FIR BEARS N3 1/2° E 188 FT

SCRIBED S 29 CS BT

8" FIR BEARS S 49° W 54 E FRK

SCRIBED T235 R9W S30 CS BT

10-26-73

THE
Surveyor

DIETZGEN NO. 385-6

C.S. FILE NO. 56/39-11

#64
OK