


Section 9, 10, 15 + 16 Twp 29S Rge 1E W

Date: 6-17-59



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: ROAD 284

C.S. File No. 56/40-52

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

NO INFO ON B.T'S

Signed

AWC