

Section 1/4 13424 Twp 29S Rge 1E W

Date: 1-8-64

How was corner identified? BYASS CAP

Condition of corner: _____

Best route to reach corner: Road # 291



C.S. File No. 56/40-60

Quadrant	NE	NW	SE	SW
Species & Size		DF 48"		DF 10"
Dist. & Bearing		N29W. 18'		S43W 18'
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:
Should lie BETWEEN
CL, 29-2 + CY.

Signed

#50 ✓
C