


Section 1/4 14423 Twp 29S Rge 1E W

Date: 1-24-45



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: Road # 291 or 2921

C.S. PRO N. 14423-67

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size	SP 26"			DF 30"
Dist. & Bearing	N55E 50IK			S61W 20IK
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				Tagged

Corner could lie
IN C.C.

Signed

#53 ✓