


Section 1/4 18419 Twp 29S Rge 1E W

Date: 9-27-51

How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: ROAD 2937



C. S. PR. No. 5640-73

Other Remarks:

| Quadrant | NE | NW | SE | SW |
|----------------------|--------------------|----|------------------------|----|
| Species & Size | <u>Cedar 18"</u> | | <u>SP 4"</u> | |
| Dist. & Bearing | <u>N 65 E 531'</u> | | <u>S 39 E 301 1/2'</u> | |
| Condition of Scribe | | | | |
| Original or Resurvey | | | | |
| Appearance of B.T. | | | <u>DOWN</u> | |
| Tags, Marks, etc. | | | | |

Signed

#59 ✓
C