


Section 1/4 19420 Twp 29S Rge 1E W

Date: 6-3-48



How was corner identified? BYASS CAP

Condition of corner: \_\_\_\_\_

Best route to reach corner: Road # 2937

C.S. File No. 50/40-74

Quadrant	NE	NW	SE	SW
Species & Size	<u>DF 13"</u>			<u>DF 28"</u>
Dist. & Bearing	<u>N34E 571K</u>			<u>S88W 251K</u>
Condition of Scribe	<u>GROWN OVER</u>			<u>GROWN OVER</u>
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				<u>Tagged</u>

Other Remarks:

Could lie in C.C.

Signed

#60 ✓  
C