


Section 1/4 7418 Twp 29S Rge 1E W

Date: 2-15-45



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: ROAD 2815. B

C. S. File No. 56/40-76

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size	<u>FIR 10"</u>			<u>Cedar 28"</u>
Dist. & Bearing	<u>N 63 E 35 1/2</u>			<u>S 28 W 28 1/2</u>
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				<u>SNA9</u>
Tags, Marks, etc.				

Signed

31 ✓
C