

COR. RENEWAL T295 R3W S24E25
S25/S26

Ren # 44

(1)

FOUND 3" IRON PIPE 10" HIGH SHOWS
RECENT BREAKAGE
FROM WHICH A;

R 34" DIAM FIR STUMP 7' HIGH BEARS
S 14° E 42 $\frac{1}{2}$ FEET (REC./ORIGINAL NOTES
FIR 18" DIAM S 15° E 42 $\frac{1}{2}$; RENEWAL
NO. 44 30" FIR S 18° E 44 $\frac{1}{2}$ FEET)
I OPEN FACE

R 40" DIAM. FIR STUMP BEARS N 58° E 11 $\frac{1}{4}$ FT
(REC./ORIGINAL N 63° E 13 $\frac{3}{8}$ FEET ;
RENEWAL NO. 47 N 75° E 16 $\frac{1}{2}$)
SCAR VISIBLE

R 12" DIAM FIR STUMP
BEARS N 48° W 11 $\frac{3}{4}$ FT
(REC./ORIGINAL NOTES
10" FIR N 45° W 7 $\frac{1}{2}$ FT ;
RENEWAL NO. 47,
N 40° W 7 $\frac{1}{2}$ FT)

(OVER)

#118 ✓

G. S. File No. 56/41-10

R ROTTED & BURNED STUMP BEARS

N 49° E 15⁰ FEET (REC/RENEWAL

NO. 44 N 61° W 18⁵)

R 30" FIR STUMP BEARS N 61° E 28⁵

(REC. 34⁰ FT) SCRIBING VISIBLE

" S 29" HAS BEEN

dislodged.

R 12" FIR STUMP BEARS S 69° E

32³ FEET (REC./RENEWAL

NO. 44 S 66° E 36² FT)

R 26" FIR STUMP BEARS S 54° W

15⁴ FT. (REC./RENEWAL NO. 44

S 41° W 13⁴ FT)

BARK SCRIBED "BT"

ALSO FIND ROTTED REMAINS
OF TREE AT SECTION CORNER.

11-7-72

PLE

Lammiman

OK 

RENEWAL T29S R3E

S26
S35
S36

REN #44

(2)

SET BRASS CAP AT SECTION

CORNER MARKED:

COUNTY SURVEYORS OFFICE

T29S R3W

S26 S25

S25 S36

1973

FROM WHICH A

R 34" FIR STUMP 7' HIGH BEARS
S 17° E 44 1/2 FEET

R 40" FIR STUMP 8' HIGH BEARS
N 7 1/2° E 13 1/2 FEET SCARS VISIBLE

R 12" FIR STUMP
BEARS N 44° W 8' FT
SCAR VISIBLE GROWN
RINGS SHOW EXTREME
SLOW GROWTH

R ROTTED & BURNED
STUMP BEARS N 58° E
16 1/2 FEET

(LOWER)

#118

U.S. FILE NO. 56/41-1C

R 12" FIR STUMP BEARS S67°E
35¹/₂ FEET

SCRIBED "S36 BT"

R 26" FIR STUMP BEARS
S41°E 14¹/₂ FEET.

SCRIBED "BT"

R ROTTED REMAINS OF
TREE BEARS S52°W 3³/₄ FEET
(REC/ORIGINAL SURVEY
S53°W 4⁶/₂ FEET / RENEWAL
NO. 44 S43°W 3⁶/₄ FT)

R 3" IRON PIPE SHOWS
SIGNS OF RECENT BREAKAGE
BEARS S56°E 3⁴/₄ FEET

11-7-73

PLE
Larry Mow

OK JLD