

$\frac{1}{4}$ $\frac{12}{13}$ T215 RTW

SEE RENEWAL # 60

FD:

1" x 1" T-IRON IN PLACE AND BENT

FROM WHICH:

16" NOW 20" D. FIR BEARS S 53° E 50± FT.
(REC. S 53° E 50± FEET)

I OPEN AND FIND GOOD SCRIBING '3'

RECORD 12" D. FIR, NOW DOWN AND BURNED
BEARS N 71° E 72± FEET
(REC. N 51½° E 75±)

BLAZE BURNT OUT.

THIS TREE MAY NOT BE IN ITS RECORD
POSITION DUE TO LOGGING ACTIVITY

FLUSH WITH GROUND

I SET A BRASS CAP ALONGSIDE T-IRON

MARKED: COUNTY SURVEYORS OFFICE
T215

#48 ✓

$\frac{1}{4}$ $\frac{512}{1}$
513

RTW

1974

PAGE 2

NEW B.T.

20" D. FIR BEARS N 11° E

115 ⁶/₁₆ FEET SCRIBED ¹/₄ SIZ CSBT

THIS CORNER LIES ON STEEP NORTH
SLOPE IN RECENT LOGGED-OVER AREA.

1-14-73

J.R.R.

P.L.E.,

OK. J.R.R.

#98

C.S. File No. 56/43-2

4-24-74

$\frac{12}{13} - \frac{1}{4}$ T215 RTW

(REN. #98)

SET STEEL FENCE POST ALONG-
SIDE BRASS CAP THIS DATE.

Gary [Signature]
BOB THURMAN
OK [Signature]

DIETZEN NO. 365-6

#98

U. S. FILE NO. 56/43-2