

1-15-74

1/4 36C17 E, 18

T295 R2W

Fd:

IRON PIPE WITH BRASS CAP ATTACHED
MARKED,

U.S. GENERAL LAND OFFICE

SURVEY

1/4
517 | 518

1917

FROM WHICH

16" ROTTEN D. FIR STOB BEARS
N 82° E 6 2/3 FEET

SCRIBING "1/4 517 BT" VISIBLE
(REC N 81° E 5.6 FEET)

DOWNED AND SHATTERED D. FIR
^{APPROX} BEARS N 39° W TAGGED AND

SCRIBING "1/4 518 BT" VISIBLE
(REC N 51° 30' W 13.9 FEET)

I MARK NEW B.T.'S

30" D. FIR BEARS N 53° E 22 3/4 FEET

✓ SCRIBED 1/4 517 CS BT"

#86

G.S. FILE No. 56/43-3

c

30" " DFIR BEARS N 24° W 29⁶ FEET
SCRIBED " 1/4 S 18 CS BT "

NOTE: RECORD NW BT, IS OUT OF
POSITION DUE TO BEING KNOCKED DOWN
BY BLOWDOWN.

BRASS CAP IS PRESENTLY LOCATED
UNDERNEATH LARGE BLOWN-DOWN
TREE

1-15-74

G.L.L

P.L.E.,

OK
G.L.L