

1-18-74

1/4 4-5 T245 R3W

(SEE RENEWAL # 63)

FD

BRASS CAP ON IRON PIPE, ~~STICK~~ IN LEAVING
AND STICKING LOOSELY IN DIRT, ALMOST
OUT OF GROUND MARKED

U.S. GENERAL LAND OFFICE SURVEY

1/4

SS | S4

1950

THIS BRASS CAP OBVIOUSLY OUT OF
POSITION.

UPON DIGGING AT POSITION ESTABLISHED
FROM 2 BT'S, I FIND A BRASS CAP,
BURIED $\frac{1}{2}$ ON ITS SIDE, IN GOOD CONDITION
MARKED COUNTY SURVEYORS OFFICE

T 245 R 3 W

1/4

SS | S4

1967

THIS CAP APPARENTLY MOVED OUT OF
POSITION AND RECOVERED WITH LODGE DIRT.

#78 ✓ C

C.S. File No. 56/43-5

Using SE & NE B.T.'s AS RECORDED
IN RENEWAL * I RESET

BRASS CAP MARKED

COUNTY SURVEYORS OFFICE

T24 S R3 W

$\frac{1}{4}$ 55 | 54

1974

1967

~~SET~~ PLACE STEEL FENCEPOST ALONGSIDE
FROM WHICH

12" HEMLOCK STUMP BEARS
N $75^{\circ}40'$ E 50.2 FEET, PREVIOUSLY
OPENED BLAZE AND SCRIBING
VISIBLE.

(REC. N $75^{\circ}40'$ E 50.2')

10" HEMLOCK STUMP BEARS
S 78° W 49.3 FEET (REC. S 270° W
46.3 FT) SCRIBING " $\frac{1}{4}$ 55 CS BT
VISIBLE

1-18-74

G.L.
P.L.E.

OK
Holl