

3-18-74

$\frac{1}{4}$   $\frac{1}{12}$  T235 R6W

FD

BRASS CAP, LYING IN FARMERS

JUNKPILE, OUT OF POSITION:

MARKED:

U.S. CADASTRAL SURVEY

BUREAU OF LAND MANAGEMENT

T 235 R6W

$\frac{1}{4}$  S  $\frac{S1}{S12}$

1957

I RESET ORIGINAL BRASS CAP AT  
IT'S RECORD POSITION FROM THE NW  
BEARING TREE A 20" NOW 36"  
D. FIR BEARING N 51° W 312<sup>2</sup> FT.  
SHOWING A WELL HEALED BLAZE.

PAGE 1

#62 ✓

C.S. FILE NO. 56/49-4C

DIETZGEN NO. 385-5

THE SE BT, A 36" NOW 40"

D. FIR BEARS  $S 48\frac{3}{4}^{\circ} E$  244<sup>9</sup> FT

(REC  $S 49\frac{3}{4}^{\circ} E$  247<sup>5</sup>), SHOWING

A WELL HEALED BLAZE. NOTE: I

DO NOT HOLD THE RECORD BEARING

AND DISTANCE AS THIS BT IS

BEING UNDERCUT BY A CREEK AND

IS LEANING HEAVILY AWAY FROM

THE CORNER.

NEW BT

AN 18" D. FIR BEARS  $S 54\frac{1}{4}^{\circ} W$

56<sup>0</sup> FT. SCRIBED  $\frac{1}{4}$  S 12 CS BT

THIS CORNER LIES IN THE FLOOD

PLAIN AND APPROX 30' WEST OF

A SMALL STREAM.

ALSO SET STEEL-FENCEPOST WITH  
SURVEY MARKER SIGN 1<sup>0</sup> FT. NORTH  
OF CORNER.

3-18-74

Mary Langley  
BOB THURMAN

OK  
HLL

DIETZGEN NO. 385 - 5