

R	1	6	R
W	2	7	W

T285

(REN # 54 IN T285 RAW)

REN # 51

FD:

BRASS CAP FIRMLY SET NEAR FENCE CORNER MARKED AS DESCRIBED IN RENEWAL # 54 (T285 RAW). THE REMAINS OF THE ORIGINAL B. OAK BT FOUND BY BYRON IN 1957 ARE NOW GONE. THE CONDITION OF THE TREES MARKED BY BYRON IS AS FOLLOWS:

18" B. OAK RECORDED AS BEARING S 77° E 27 1/2 FT. IS NOW DOWN. FD. BEARING TREE TAG ATTACHED BUT SCRIBED PORTION OF TREE IS BURIED.

16" LAUREL BEARING N 66 1/2° W 82 1/2 FT., IS NOW A BURNT-OUT SHELL, ALL SCRIBING HAS BEEN DESTROYED.

18" LAUREL BEARING N 13° E 87 1/2 FT., IS NOW A BROKEN STOB. WE FIND PLAIN SCRIBING "BT" ON BASE, SCRIBED AREA ON REMAINDER OF TREE IS BURIED.

T28.4 #117 ✓
T28.5 #137 ✓

U.S. File No. 56/51-15 Page 1
C.

WE MARK THE FOLLOWING BT'S:

6" MADRONE BEARS N 54° E 44 $\frac{1}{2}$ FT.,
SCRIBED "TZBS R4W S 6 CS BT"

5" D. FIR BEARS N 57° W 8 $\frac{1}{2}$ FT.,
SCRIBED "TZBS R5W S 1 CS BT"

8" D. FIR BEARS S 16 $\frac{1}{2}$ ° W 168 $\frac{1}{2}$ FT.,
SCRIBED "TZBS R5W S 12 CS BT"

NO TREES NEAR TO THE SE.

6-3-74

Gary L. Langley
PETER L. EARLE

OK
[Signature]