

17 | 16 T325 RIW

 $\frac{1}{4}$

(REN. # 31)

FD

BRASS CAP MARKED:

COUNTY SURVEYOR'S OFFICE

T325 RIW

 $\frac{1}{4}$ S17 | S16

1968

BRASS CAP WAS FOUND OUT OF THE GROUND,
APPARENTLY MOVED DURING LOGGING OPERATIONS.
THE REMAINS OF THE ORIGINAL BT'S NOTED
AS FOUND BY CO. SURVEYOR'S OFFICE IN 1968
HAVE ALSO BEEN DESTROYED.

WE RESET THE BRASS CAP AT THE CORNER
POINT AS DETERMINED FROM THE BEARING
TREES MARKED BY THE COUNTY SURVEYOR
IN 1968 AS FOLLOWS:

A 14" NOW 15" HEMLOCK, NOT R. FIR, BEARS
N 89° E 65' FT., WITH SCRIBING
" $\frac{1}{4}$ S 16 CS BT" VISIBLE ON UNHEALED
BLAZE.

A 12" NOW 14" HEMLOCK, NOT R. FIR, BEARS
S 45° W 26⁸ FT., WITH SCRIBING "1/4 S 17
CS BT" VISIBLE ON UNHEALED BLAZE.

WE DO NOT MARK ANY NEW BT'S

G-4-74

Ray Longley

PETER LEARLE

OK
[Signature]

DIETZGEN NO. 385-6