

~~28 24~~~~26 25~~

T305 RBW

(SEE RENEWAL # 3)

Fo:

4" X 4" SCRIBED WOOD POST, NEARLY ROTTED  
OFF, MARKED "S 23" ON NW FACE

"S 24" ON NE FACE

"S 25" ON SE FACE

AND "S 26" ON SW FACE

WITH STEEL FENCE POST SET ALONGSIDE,

FROM WHICH:

A 28" NOW 32" D. FIR BEARS N71°E  
43<sup>7</sup> FT., SCRIBING VISIBLE ON UNHEALED  
BLAZE

A 36" NOW 48" D. FIR BEARS S21°E  
108<sup>8</sup> FT., (REG. S21°E 110<sup>2</sup> FT.) SCRIBING  
VISIBLE ON UNHEALED BLAZE.

WE FIND YEW WOOD REMAINS IN APPROX.  
POSITION OF ORIGINAL NE BEARING TREE, NO  
MARKINGS FOUND.

#114 ✓

LOGGING ACTIVITY HAS DESTROYED ALL OTHER  
RECORDED BT'S FOR THIS CORNER.

WE REMOVE THE SCRIBED CEDAR POST AND  
REPLACE IT WITH A BRASS CAP SET FLUSH WITH  
THE GROUND, MARKED:

COUNTY SURVEYOR'S OFFICE

T305

S23 | S24

S26 | S25

RBW

1974

RESET SCRIBED WOOD POST AND STEEL FENCE  
POST ALONGSIDE BRASS CAP AND MARK  
THE FOLLOWING NEW BT.,

AN 8" D. FIR BEARS N 44° W 73<sup>7</sup> FT.,  
SCRIBED "T305 RBW S23 CS BT"

NO TREES NEAR TO SW

COMPASS DECLINATION SETTING 20° EAST

6-26-74

Gary Langley  
PETER EARLE

c.s. 56/51 - 26