

8-5-74

$\frac{1}{4}$   $\frac{3}{10}$

T295 R.1E

FD:

IRON PIPE WITH BRASS CAP ATTACHED

MARKED:

U.S. GENERAL LAND OFFICE SURVEY

$\frac{1}{4}$   $\frac{33}{510}$

1921

THIS MONUMENT WAS FOUND SITTING NEARLY  
OUT OF THE GROUND, SLIGHTLY BENT AND  
DISORIENTED. THE AREA AROUND THE  
CORNER HAS BEEN LOGGED SOME YEARS  
AGO.

WE FIND A 20" D. FIR STUMP, 4 FT. TALL  
BADLY DETERIORATED WHICH WE OPEN AND  
FIND GOOD SCRIBING " $\frac{1}{4}$  S3 BT"

WE RESET THE BRASS CAP AT THE RECORD  
BEARING AND DISTANCE FROM THE ONLY  
REMAINING BEARING TREE, AN ORIG 18"

#73 ✓

C. S. File No. 57/2-11

PAGE 1

C

DIETZGEN NO. 385-6

NEW NW BT 7" P. PINE

N 22° W

172 LVL

1/4 S 3 CS BT

NEW SW BT 4" " SUGAR PINE

S 35 1/2° W

41 1/8 @ 4 1/2° .99692 41 1/2

1/4 S 10 CS BT

FIR, NOW A 20" FIR STUMP BEARING N 42° E  
16  $\frac{1}{2}$  FT.

WE MARK THE FOLLOWING BEARING TREES:

A 7" PONDEROSA PINE BEARS N 22° W  
17  $\frac{1}{2}$  FT., SCRIBED "1/4 S B CS BT"

A 4" SUGAR PINE BEARS S 35  $\frac{1}{2}$ ° W  
41  $\frac{1}{2}$  FT., SCRIBED "1/4 S 10 CS BT".

8-5-74

Larry Langley  
PETER L. EARLE

OK  
