

10-2-74

T295

25	30
36	31

R1E R2E

FD:

(ORIG. 18"X12"X5")

A BASALT STONE, 14"X12"X5" AFFIRMLY
 SET 9" IN THE GROUND, MARKED WITH A "T" ON TOP,
 WE DO NOT FIND ANY NOTCHES ON THE STONE;

FROM WHICH;

AN ORIG. 7" NOW 10" D. FIR BEARS N 82° E
 15 1/2 FT., SCRIBING VISIBLE ON UNHEALED
 BLAZE.

AN ORIG. 10" NOW 16" D. FIR BEARS S 70° E
 13 1/2 FT., WELL-HEALED.

AN ORIG. 12" NOW 19" D. FIR BEARS
 S 77° W 13 1/2 FT., WELL-HEALED.

A D. FIR TREE MARKED IN A RETRACEMENT
 SURVEY, ORIG. 20" NOW 27" IN DIAMETER
 BEARS N 8° W 31 1/2 FT., WELL-HEALED.

#12 T292E ✓

#85 T29-1E ✓

57/8-6
 C. S. File No. ~~587~~ PAGE 1 C

DIETZGEN NO. 3855-5

THERE IS NO TRACE OF THE ORIGINAL NW BEARING
TREE.

AT THE CORNER POINT, WE SET A 1" X 30" IRON
PIPE WITH BRASS CAP ATTACHED, MARKED

COUNTY SURVEYOR'S OFFICE

T29S

S 25 | S 30

S 36 | S 31

R 1 E

R 2 E

1974

AND DEPOSIT THE ORIGINAL STONE ALONGSIDE.

COMPASS DECLINATION SETTING: 20° EAST.

10-2-74

Larry L. Langlit

PETER L. EARLE

OK
JL

57/8-6

C. S. File No. ~~57/7~~

9-30-74

$\frac{4}{9} / \frac{3}{10}$

T305 R2W

(SEE REN. # 51)

FD:

A STONE AND $\frac{1}{2}$ " I. PIPE, BOTH FIRMLY SET AND IN GOOD CONDITION AT THE CORNER POINT.

WE FIND 3 ORIG. BT'S IN THEIR PROPER POSITION AND MARKED AS DESCRIBED IN THE ORIG. FIELD NOTES. THE ORIG. SE BEARING TREE IS NOW DEAD AND DOWN.

WE ALSO FIND 3 BEARING TREES IN POSITION AND MARKED AS DESCRIBED IN RENEWAL #51.

NOTE: THE AREA IMMEDIATELY NE OF THE CORNER HAS BEEN RECENTLY LOGGED.

9-30-74

Larry L. Langlet

PETER L. EARLE

#185 ✓

OK
[Signature]

5778-6

C. S. File No. 5779 C

DIETZGEN NO. 3855-6