

11-29-74

MEANDER CORNER $\frac{22}{27}$ T21S R12W
ON RIGHT BANK OF UMPQUA RIVER.

(SEE GEN. COR. F2 E. 36)
E. CS. FILE 41/180

FD:

$\frac{5}{8}$ "

NOT OF RECORD.

IRON ROD SET FLUSH IN A CONCRETE
DRIVEWAY ON THE EAST SIDE OF U.S.
HIGHWAY #101 IN GARDNER. THIS
MONUMENT WAS FOUND BASED ON
INFORMATION SHOWN ON OREGON STATE
HWY. DEPT. DRAWINGS, # 4B-26-2,
1B-26-23, AND 5B-31-5 FILED
RESPECTIVELY IN THE DOUGLAS COUNTY
SURVEYOR'S OFFICE AS STATE HIGHWAY
MAPS C-8, C-10, AND D-1. STATE HWY.
DEPT. OFFICIALS INDICATED DURING A
TELEPHONE CONVERSATION THAT THE FIELD
NOTES OF THEIR ROAD SURVEYS DO NOT
SHOW THIS CORNER AS BEING RECOVERED.

TO PRESERVE THIS LOCATION, WE NOTE THE
FOLLOWING BEARING OBJECTS;

#39 ✓

S. File No. 57/12-5

PAGE 1^C

THE SW CORNER OF A HOUSE, (JONES
RESIDENCE) BEARS $N 25^{\circ} E$ $22 \frac{1}{2}$ FT.

THE NW CORNER OF A TWO-CAR GARAGE
BEARS $S 65^{\circ} E$ $36 \frac{5}{8}$ FT.

A BOLT, SET FLUSH IN THE SOUTHERLY EDGE
OF THE DRIVEWAY BEARS $S 14^{\circ} E$ 8° FT.

NOTE: REN. # 36 MISTAKENLY DEALS WITH
THE WRONG CORNER.

11-29-74

Larry J. Langley
PETER L. EARLE

OK
JL