

$$\frac{1}{4} \frac{7}{18}$$

T285 R3W

(SEE REF. # 9)

FD:

1" IRON PIPE, FIRMLY SET WITH BRASS CAP
ATTACHED, MARKED:

COUNTY SURVEYOR'S OFFICE

T285

$$\frac{1}{4} \frac{37}{518}$$

R3W

1957

FROM WHICH:

AN ORIGINAL BEARING TREE, A 12" NOW
18" INCENSE CEDAR BEARS S 61° E 27'
FT., ALIVE AND WELL-HEALED.

THE ORIGINAL NW BEARING TREE HAS
BEEN DESTROYED.

A 14" CEDAR MARKED BY THE COUNTY
SURVEYOR IN 1957, NOW A 20" STUMP
BEARS N 30 $\frac{1}{4}$ ° W 50° FT., WITH
SCRIBING "BT" VISIBLE.

14" RED CEDAR S 57° W

21³ @ 28°

.8829

18⁸
—

"1/4 S 18 CSBT"

WE MARK THE FOLLOWING NEW BEARING
TREE:

A 14" RED CEDAR BEARS S 57° W 18⁰ FT.,
SCRIBED "1/4 S. 18 CS BT"

NOTE:

THIS CORNER IS LOCATED APPROX 100 FT.
EAST OF BLM RD. # 28-4-132.

COMPASS DECLINATION SETTING: 20° EAST

1-23-75

Gary L. Anglit
PETER L. EARLE

OK
[Signature]

DIETZEN NO. 385-6