

1-27-75

WITNESS CORNER TO

$\frac{1}{4}$ 35 | 36 T 265 R 7W

(SEE REFS # 35 & 90)

Fd:

1" IRON PIPE, FIRMLY SET WITH BRASS CAP ATTACHED,
AND MARKED AS DESCRIBED IN REF # 90,
FROM WHICH WE FIND THE FOLLOWING CORNER
ACCESSORIES;

A $\frac{3}{8}$ " IRON ROD BEARS S 48° W 46 FT.
AND A 16" W. OAK, NOW A STUMP BEARS EAST
5 $\frac{0}{10}$ FT., WITH SCRIBING "WC $\frac{1}{4}$ 35 36 CS BT"
VISIBLE.

WE NOTE A NEW BEARING OBJECT AS
FOLLOWS:

A $\frac{3}{8}$ " I. ROD AT ENGINEERS STATION 222+10
POC 35' LEFT OF THE CENTERLINE OF
CO. RD. # 53 (ELGAROSE RD) (EAST SIDE
OF ROAD) BEARS S 3° E 275 $\frac{7}{10}$ FT.

#101 ✓

C

00/10

T. 100

@ STA 222+10

POC

35' LEFT

S 3° E

200° @ 4'

.99756

199³

76³ @ 3°

.99863

76²

2757

WE NOTE THAT TWO BEARING TREES ARE STILL
 IN EXISTENCE FOR THE TRUE $\frac{1}{4}$ CORNER, ONE
 IS THE ORIGINAL SE BEARING TREE WITH SCRIBING
 " $\frac{1}{4}$ " VISIBLE, AND THE OTHER IS THE NW
 BEARING TREE REPORTED IN 1959 BY BYRON
 AND GODFREY (SEG. REV. #35)

WE DO NOT SEARCH FOR ANY EVIDENCE OF
 RECORD MONUMENTS AT THE TRUE $\frac{1}{4}$ CORNER.

NOTE:

THE DISTANCE TO THE ORIGINAL SE BEARING
 TREE AS SHOWN IN REV. # 35 IS ERRONEOUS,
 IT SHOULD BE $112 \frac{2}{3}$ FT., NOT $12 \frac{2}{3}$ FT.

COMPASS DECLINATION SETTING 120° EAST

1-27-75

Gary L. Langfit

JOHN E. NORDLING

OK *[Signature]*