

1-28-75

CENTER $\frac{1}{4}$ SEC 27 T22S R8W

FD:

2 BEARING TREES MARKED IN 1964 DURING A SURVEY TO SUBDIVIDE SECTION 27. THE CORNER MONUMENT HAS BEEN DESTROYED BY A LAND-SLIDE. IT IS NOW IMPRACTICAL TO RE-ESTABLISH THE CORNER AT IT'S TRUE LOCATION, WE THEREFORE SET A WITNESS CORNER AS FOLLOWS:

FROM THE TRUE CORNER AS DETERMINED BY RECORD MEASUREMENTS FROM THE FOLLOWING BT'S:

AN 8" NOW 12" W, FIR BEARING $N79^{\circ}E$
 $31^{\frac{1}{2}}$ FT., ALIVE AND WELL-HEALED.

AND A 10' NOW 16" W, FIR BEARING $S47^{\circ}E$
 $19^{\frac{5}{8}}$ FT., ALIVE AND WELL-HEALED

WE SET A WITNESS CORNER FOR THE CENTER $\frac{1}{4}$ CORNER OF SECTION 27, $195^{\frac{0}{8}}$ FT. NORTH OF THE TRUE CORNER.

DIETZEN NO. 385-6

16" W. Fr.

22" @ 32° .54805 494

110° @ 19 1/2°

.94264

1032

88° @ 5°

.9945

881

1918

32

NORTH
TO WC

1950

16" W. Fr. S 61 1/2° W

14° LVL

" WC C 1/4 S 27 CS BT "

13" D. Fr. N 16° W

48 LVL

" WC C 1/4 S 27 CS BT "

C S O

F225

WITNESS COR.

195 FT. SOUTH TO



CENTER 1/4 S. 27

R B W

1975

AT THE WITNESS CORNER WE SET A 1" X 30"
IRON PIPE, WITH BRASS CAP ATTACHED,
MARKED

COUNTY SURVEYOR'S OFFICE

T22S

WITNESS COR.

195 FT. SOUTH TO



CENTER $\frac{1}{4}$ S. 27

R 8 W

1975

FROM WHICH WE MARK THE FOLLOWING BEARING
TREES FOR THE WITNESS CORNER:

A 16" W. FIR BEARS S 61 $\frac{1}{2}$ ° W 14° FT.,
SCRIBED " WC C $\frac{1}{4}$ S 27 CSBT".

AND A 13" D. FIR BEARS N 16° W 4 $\frac{1}{2}$ FT.,
SCRIBED " WC C $\frac{1}{4}$ S 27 CSBT".

NOTE:

THE WITNESS CORNER IS LOCATED APPROX.
90 FT. NORTH OF GOULD CREEK RD. (BLM 22-8-22)
COMPASS DECLINATION SETTING: 20° EAST

U.S. File No. 5747 *OK*

1-28-75
John E. Nordling
JOHN E. NORDLING

DIETZGEN NO. 385-6