

18 | 17 T295 R2W

(SEE REN\* 86)

FD

BRASS CAP, OUT OF THE GROUND AND MOVED APPROX. 30 FT. DOWNHILL FROM ITS PROPER POSITION BY LOGGING OPERATIONS.

THE REMAINS OF BOTH ORIGINAL BT'S HAVE ALSO BEEN DESTROYED.

THE TWO ADDITIONAL BT'S MARKED AS NOTED IN REN. \* 86 ARE NOW BOTH STUMPS. THEY ARE IN THE POSITIONS AS NOTED IN REN. \* 86.

HOWEVER, ONLY THE SCRIBING "CS BT" REMAINS ON THE NW TREE. THE FULL SCRIBE IS VISIBLE ON THE NE BT.

AT THE CORNER POINT, WE RESET THE ORIGINAL MONUMENT, A 1" I. PIPE WITH BRASS CAP ATTACHED, MARKED:

U.S. GENERAL LAND OFFICE SURVEY

18 | 17

1917

C. S. File No. 57/21-14

Page 2  
C

\* 87 T29-5 ✓

TO WHICH WE ADD THE MARKINGS:

"CS 1975"

WE ALSO PLACE A STEEL FENCEPOST WITH SURVEY MARKER SIGN ATTACHED NEAR THE CORNER.

4-29-75

Gary L. Langley

PETER L. EARLE

of [signature]

# 87-129.2

DIETZGEN NO. 385-6