

8-7-75

T215
33   34
3
T225

RBW

FD:

REMAINS OF ONE BT MARKED IN 1945, A  
 FRAGMENTED, ROTTEN HEMLOCK STUMP BEARING  
 N 46° 45' W 57 1/2 FT., WITH SCRIBING  
 "W 533 BT" VISIBLE.

THE BRASS CAP SET IN 1945 AND ALL OTHER  
 CORNER ACCESSORIES HAVE BEEN DESTROYED.

DUE TO EXTREMELY STEEP SLOPES, SHALLOW  
 SOIL AND LOOSE ROCK, IT IS IMPRACTICAL  
 TO SET ANY TYPE OF PERMANENT  
 MONUMENT. WE DO, HOWEVER, PLACE A  
 STEEL FENCEPOST AT THE CORNER POINT.

WE MARK THE FOLLOWING NEW BT'S:

AN 8" RED ALDER BEARS N 55° W  
 34 1/2 FT., SCRIBED "T215 RBW 533  
 CS BT" ON A DOUBLE BLADE.

#134 T225  
 #23 T215

LITTON NO. 105-B

AND A 7" D. FIR BEARS N 51° E 23<sup>6</sup> FT.,  
SCRIBED "TZIS RBW S34 CS BT" ON  
A DOUBLE BLAZE.

COMPASS DECLINATION: 20° EAST

8-7-75

*Larry L. Langley*

CLELL E. GOODWIN

M. LENORA LADIG

A. VIC CANGIE

*JK*  
*[Signature]*