

9-4-75

$\frac{1}{4}$   $\frac{10}{15}$  T295 R1E

WITNESS CORNER

Fd:

IRON PIPE WITH BRASS CAP ATTACHED AND MARKED AS DESCRIBED IN THE OFFICIAL RECORD.

THIS PIPE IS LOOSELY SET, EXTENDING APPROX 18" ABOVE GROUND AND ORIENTED IN THE WRONG DIRECTION. THERE IS NO EVIDENCE OF THE RECORD BT'S AT THIS LOCATION.

THE COR. LIES APPROX 500 FT. WEST OF SOUTH UMPQUA FALLS (RECORD WEST 301<sup>5</sup> FT.) AND APPROX 50' NORTH OF THE RIGHT BANK OF THE RIVER.

DUE TO LACK OF EVIDENCE AND CONFLICTING CALLS, WE DO NOT MONUMENT.

9-4-75

Darryl J. Langlotz  
GLENN E. GOODWIN  
A. VIC CANGIE  
M. LENORA LADIG

OK  
JAL

#92 ✓

CS 170 57 136-4

DIETZGEN NO. 3855-6