

9-24-75

7 | 8

T275 R3W

$\frac{1}{4}$

FP:

ORIG. 24" D FIR, NOW A 30" SNAG BEARING
S 80° E 13² FT., NO MARKS VISIBLE.

THE ORIGINAL NW BEARING TREE HAS BEEN
DESTROYED.

A 22" NOW 26" MADRONE MARKED BY CADASTRAL
ENGINEERS IN 1958 BEARS S 84¹/₂° E 35⁵ FT.,
WITH SCRIBING VISIBLE ON UNHEALED BLAZE.

AND A 13" NOW 18" INCENCE CEDAR, IN GOOD CONDITION,
ALSO MARKED IN 1958.
A BEARS N 65° W 37⁵ FT., WITH SCRIBING
VISIBLE ON UNHEALED BLAZE.

THE BLM BRASS CAP SET IN 1958 HAS
BEEN DESTROYED.

AT THE CORNER POINT, WE SET A 1" X 30" IRON
PIPE, WITH BRASS CAP ATTACHED, MARKED:

#123^v_c

U.S. File No. 57/36-10 PAGE 1

$36^{\frac{3}{4}} @ 5^{\circ} .9962$

$36^{\frac{2}{4}}$

~~N 64° W 0 $\frac{60}{60}$~~

~~STAKE TO CAP~~

DOUGLAS CO. SURVEYOR

T 27 S

 $\frac{1}{4}$

S 7 | S 8

R 3 W

1975

NOTE:

THE SCRIBING ON THE N W BEARING TREE
HAS BEEN PARTIALLY DEFACEED BY FIRE.
WE RESCRIBE " $\frac{1}{4}$ S 7 CS BT" ON A SINGLE
BLAZE ABOVE THE PRESENT BLAZE.

THIS CORNER IS LOCATED ON A STEEP NORTH
SLOPE ALONG AN OLD CAT FIRE TRAIL.

COMPASS DECLINATION SETTING: 20° EAST

9-24-75

Doug J. Jamalis

PETER L. EARLE

JIM H. COOK

01/5/80
[Signature]

123

C. S. File No.

57/36-10