

RENEWAL

T215 R9 flow

T205 R9W	
CC 531	
S1	S6
R10W	R9W

WC
T215

FOUND

1. A CEDAR 40 INCH NOW 52 INCHES IN DIAMETER BEARS S 42° E 44¹/₂ FEET (REC. 46¹/₂ FEET), BLAZED.

2. A CEDAR 45 INCH NOW 55 INCHES IN DIAMETER BEARS N 38° W 21¹/₂ FEET, SCRIBED "WCC T215 R9, 10 W".

MAPLE BEARING TREE NOT FOUND, BEARING AND DISTANCE RECORDED FAILS IN LARGE GROWTH OF MAPLES IN SLIDE AREA.

RENEWAL

SET BRASS CAP AT WITNESS CORNER TO CLOSING CORNER STAMPED,

43 T21-10 ✓
27 20-9 ✓
25 = 20-9 ← ²⁵/₂₁

C.S. File No. 57/39-4

DIETZGEN NO. 385-6

(RENEWAL)

"

COUNTY SURVEYOR'S OFFICE "

T 20 S R 9 W
C.C. 5131

S 1 | S 6
R 10 W | R 9 W

W C

T 21 S

1975

NOTE:

CORNER LIES NEAR SOUTH BANK
OF SMITH RIVER, NEARBY
DIRECTLY ACROSS RIVER FROM
FENCE RUNNING NORTH & SOUTH
AT EAST END OF FAWN CREEK
PARK.

11-5-75

L. E. MONREAN

P. L. E.

D. L. S.

OK
[Signature]

C.S. File No. 57/39-4

2)