

12-17-75

16 | 15

1/4

T 305 BZW

(SEE REN. # 61)

Ep:

1" X 1" ANGLE IRON SET BY MARKHAM (REN. # 61)
IN PLACE AT THE CORNER, FROM WHICH WE
FIND THE REMAINS OF THE ONLY EXISTING
ORIGINAL BT, A ROTTEN STUMP WITH SCRIBING
"BT" VISIBLE ON ROTTING FACE BEARS
S 20° E 3 3/4 FT.

THE ORIGINAL NW BEARING TREE IS GONE.

WE FIND MARKHAM'S BEARING TREES AS

FOLLOWS:

A 24" INCENSE CEDAR (REC. 30" DIA.), ~~was~~
ALIVE WITH SCRIBING PARTIALLY VISIBLE ON
UNHEALED BLAZE BEARS S 35° W 40[±]
FT., (REC. S 32° W 40[±] FT.)

#190 ↓

G. S. File No.

57/39-38

PAGE 1

DIETZGEN NO. 385-B

MARKHAM'S NE BT

33⁷/₂ @ 23° .9205

31°

MARKHAM'S SW BT

22²/₂ @ 25° .9063

20¹/₂

A 17" D. FIR (REC. 18" DIA.), ALIVE WITH SCRIBING
VISIBLE ON PARTIALLY HEALED BLAZE
BEARS N 81 1/2° E 31 5/8 FT. (REC. N 80° E
33 0 FT.)

AND A 45" D. FIR (REC. 50" DIA.) WITH MARK
SCRIBING VISIBLE, BEARS S 35° E
20 1/2 FT., (REC. S 35° E 21 7/8 FT.)

AT THE CORNER POINT, WE SET A 1" X 30"
IRON PIPE, WITH BRASS CAP ATTACHED, MARKED:

DOUGLAS CO. SUPERIOR
T 30 S R 2 W

S 16 | S 15
1/4

1975

NOTE: WE PLACE ANGLE IRON ALONGSIDE
BRASS CAP.

NOTE: THIS CORNER IS LOCATED IN A N-S
FENCELINE APPROX. 150 FT. WEST OF
BLM ROAD # 30-2-14.0. 12-17-75

COMPASS DECLINATION:
20° EAST

A. VIC LANGIE

Larry L. Langie
C. E. GOODWIN
M. LENOEA LADIG

DIETZGEN NO. 3885-6

U.S. FILE NO. 57/29-38