

CONTINUED
CORNER:

PUBLIC LAND CORNERS - WEYERHAEUSER COMPANY - SPRINGFIELD
W $\frac{1}{4}$ Sec. 34, T25S, R3W

	Present Condition 10/31/1978:
2. Vine Maple Clump N60W 6.6'.	As above.
3. 18" Incense Cedar N86E 27.7' scribing plainly visible.	As above
4. 24" Fir S85W 23.6' Face grown over	As above.
Referenced with "W" nails and Weyerhaeuser Co. plates on:	
3. 18" Incense Cedar N85E 27.0'.	"W" nail and plate intact.
4. 32" Fir S86W 23.5'.	Plate gone, "W" nail intact but stump moved out of its original position. (Note discrepancy in dia. of stump - actually is a 24" fir stump).
Added 1 new reference with W Nail and plate	10/31/1978:
48" Fir N47E 76.4'.	
Work done for Weyerhaeuser Company by: Glen McChesney - 10/31/1978	Under the Supervision of: Frank O. Williams.

FILED
RECEIVED *7/8*
DEC 22 1980
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Frank O. Williams
OREGON
JULY 12, 1968
FRANK O. WILLIAMS
0875