

FILED
RECEIVED

JUL 14 1984

OREGON CORNER RESTORATION FORM

Section 17 Township 25S Range 2W

County Douglas Date 10-30-84

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

S.W. Sec. Cor.

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. Set in 1978 by BLM

Monument(s) & Accessories Found: (Condition and Source)

Found: 3 1/4" brass cap on a 2 1/2" Galv. I.P. flush with grd. with a 1/2" I.P. extending 10" above cap, set along side B.C.I.P. - also found: 15" Fir bears S85°E, 16.40 Ft. closed face (1960)

14" Fir bears S74°W, 23.00 Ft. closed face (1960)

15" Fir bears N45°30'W, 19.29 Ft. closed face (1960)

15" Fir bears N11°30'E, 34.20 Ft. closed face (1960)

9" down and decaying Yew alongside roothole, which bears S57°W, 26.4 Ft.

No scribe marks found.

Monument Detail

Sketch

T25S R1W

518	517
519	520

1978

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 19°45'E

Firm/Agency Champion International Corp.

Address P.O. Box 1328
Roseburg, Ore. 97470

Party Chief R. Geisler

Notes D. Turner

Witness _____

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald G. Geisler

OREGON
JULY 16, 1982
RONALD G. GEISLER
1988