

FILED <sup>2/</sup>  
RECEIVED LC

APR 1 1978

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.  
<sup>2/</sup>

RESTORATION OF CORNER  
PARCEL 1

MINOR LAND PARTITION  
M 60-30

in Section 5, T30S, R5WWM  
Douglas County, Oregon  
March 27, 1978

Found:

1/2-inch iron rod at southeast corner,

5/8-inch iron rod at southwest corner on  
Woodcrest Drive,

5/8-inch iron rod at 107.19 feet along  
Woodcrest Drive, being the point of curve,  
the same having a central angle of  $0^{\circ}25'51''$   
bearing to the right, a radius of 375 feet  
and a long chord of 2.82 feet,

1/2-inch iron rod at the northwest corner

of Parcel 1 of the above Minor Land Partition.

Reset Northeast corner as follows:

Set up on iron rod described as point of curve,  
sighted iron rod at southeast corner, turned  
interior angle of  $90^{\circ}27'28''$  to the left, meas-  
ured 150.05 feet along line and set a point.

Occupied said point and sighted iron rod de-  
scribed as point of curve, turned interior  
angle of  $89^{\circ}42'50''$  to the left and measured  
110.01 feet to the 1/2-inch iron rod at the  
southeast corner.

Set 1/2 inch iron rod in the northerly third  
of a gravel access road giving onto Parcel  
2 of said Minor Land Partition.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Harrison M. Munger*

OREGON  
February 2, 1978  
HARRISON M. MUNGER  
1576

AROLD COX

G. S. File No. 58/166