

TOWNSHIP 32 SOUTH  
RANGE 1 WEST

FILED  
RECEIVED *1/h*  
MAY 26 1981  
COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

## FIRST RE-ESTABLISHMENT

One Quarter corner common to Sections 2 and 11, Township 32 South, Range 1 West, W. M.

From the following original evidence at the location described below, set a 2 x 32 ins. galvanized iron pipe 28 ins. in the ground, for the corner, with a 2½ ins. diam. brass cap mkd:

T32S R1W

$$\frac{1}{4}S \frac{2}{11}$$

C.S.  
1981

Original bearing trees recorded by R. Moore in 1883, fd. as follows:

Rotted Fir stump remains with portions alongside containing old axe work and scribed (partial) "BT" brs. record; S20°W, 3.30 ft. to estimated original position of scribed face.

Rotted Fir root and stump remains, containing old axe work, fd. at record location of original Northwest bearing tree.

The original stone is now gone.

SEE also Jackson County field notes, page 73-74, dated 5/7/81.

A fd. 2 ins. diam. aluminum pipe, projecting 5 ins. with aluminum cap mkd:

T32S R1W W.M.

$$\frac{1}{4} \frac{2}{11}$$

1980

PLS 1035

set by proportionate method, on Survey No. 8498, dated 1980, bears S86°24'E, 48.75 ft.

Mound stones around corner, mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

Douglas Fir, 9 ins. diam., brs. S27°54'W, 17.00 ft (5.18 m).

Hemlock, 13 ins. diam., brs. N63°50'W, 21.10 (6.43 m).

Corner lies on steep (90%) North slope an estimated 400 ft. North of road along top of Umpqua Divide ridge top.

Ed McGinty  
County Surveyor

May 7, 1981

R.Frost

R.Templin

Witness: T.Newcomb, U.S.F.S.

p-73-74