



T. 23-5  
Sw 1/4 5-20

CS 58/192

Number \_\_\_\_\_

H.T. McAlister.

August \_\_\_\_\_ 1947.

Township 23 South Range 5 West.

Begin at the Southwest corner of section 20 in the above Tp. & Rg. This corner only had two bearing trees. One tree had fallen S.W. standing and in a fine condition, which I remarked to small iron in place for corner thence I run N39 43 E9 on section line 16.22 center of County Road at 20.03 Rock with a cross and on line with fence running South Now returned to center of County road and run as follows

North	16	degrees	East	4.30	chains
"	46	"	"	2.67	"
"	16 & 30	"	"	2.16	"
"	44	"	"	2.37	"
"	25	"	"	3.21	"
"	14	"	West	3.46	"
"	65	"	East	5.02	"
"	II	"	"	1.30	" to

property line in center of road.

Now return to I/16 section corner North of section corner which is already established with an iron rod and run South 39 43 East 30.60 chains to the center of County Road. Containing 43.49 acres which includes 1/2 of 60 ft. Highway right-of-way.

CS 58/192-3b