

M 84-35

SECTION LINE SURVEY for NICHOLAS COUNTS in the Northeast  $\frac{1}{4}$ , Section 22, Township 29 South, Range 5 West, Willamette Meridian, Douglas County, Oregon.

Survey began with the location of the North quarter corner ( brass cap ) and the Northeast corner (  $1\frac{1}{2}$  inch iron pipe ) of Section 22, Township 29 South, Range 5 West, Willamette Meridian. All bearing trees appeared in good shape.

I first ran a random line between the two above mentioned corners and then returned to the Northerly quarter corner and ran North  $88^{\circ} 29' 00''$  West and set the following iron rods in this North line of Section 22. Note that this line was ran before ( M8-70 ) and that my " Base of Bearing " is called North  $88^{\circ} 29' 00''$  West.

At 550.00 feet I set a  $\frac{5}{8}$  inch iron rod and find a  $\frac{1}{2}$  inch iron rod North 0.46 feet and West 0.20 feet from this point. ( not recorded )

At 1276.29 feet or 726.29 feet further I set a  $\frac{5}{8}$  inch iron rod.

At 1838.25 feet or 561.96 feet further I set a  $\frac{5}{8}$  inch iron rod.

This rod was set at the intersection of the section line and the Westerly right of way of the road into Springbrook Acres Subdivision. ( RM2-47 )

DATE OF SURVEY: May 29, 1980  
SURVEYOR: John H. Markham Jr.  
Myrtle Creek, OR.  
ph. 503-863-4590

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
SEPTEMBER 23, 1977  
JOHN H. MARKHAM, JR.  
1261