

Shaner Engineering, Inc.

PLANNING • SURVEYING • ENGINEERING
P. O. BOX 1430
ROSEBURG, OREGON 97470

December 6, 1982

SECTION CORNER COMMON TO SECTIONS 1, 2, 11 & 12, T27S, R6W, W.M.

On July 16, 1982, I tied into the above section corner and found:

a 1" iron pipe with a 2½" brass cap marked: "COUNTY SURVEYORS OFFICE, S1, S2, S11 & S12, T27S, R6W" and from which a:

32" black oak original BT, With rotted out face, bears N22½°E, 24.2 feet.

Oak stump, original BT, now burned and rotted, bears S62°W, 66.9 feet.

36" white oak original BT, with healed over face, bears N85°W, 90.4 feet to face.

8" madrone BT with rotted face, bears S55°E, 9.6 feet.

14" black oak BT with healed over face, bears S57°W, 40.5 feet.

6" black oak BT, scribes visible, bears S72°E, 19.1 feet.

10" black oak BT, scribes visible, bears N74°E, 20.0 feet. (Record N84°E).

REGISTERED
PROFESSIONAL
LAND SURVEYOR

B A Shaner

OREGON
OCT. 4 1987
BRUCE A SHANER
432

FILED
RECEIVED *JS*

DEC 7 1982

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#164X

C. S. File No. 58/229-17

C